

Type	Hits	Search Text	DBS	Time Stamp	Comments	Error Definition
130	BRS 64	345/541.ccls.	USPAT	2004/07/2 1 11:08		
131	BRS 0	345/541.ccls. and 345/547.ccls.	USPAT	2004/07/2 1 19:14		
132	BRS 79	345/541.ccls.	USPAT; US-PGPUB; EPO; JPO	2004/07/2 1 11:09		
133	BRS 20	345/541.ccls. and 345/501-503.ccls.	USPAT; US-PGPUB; EPO; JPO	2004/07/2 1 13:11		
134	BRS 130	345/\$.ccls. and first near portion same first near2 frame	USPAT; US-PGPUB; EPO; JPO	2004/07/2 1 13:12		
135	BRS 88	345/\$.ccls. and first near portion same first near2 frame and (vga processor)	USPAT; US-PGPUB; EPO; JPO	2004/07/2 1 13:12		
136	BRS 82	345/\$.ccls. and first near portion same first near2 frame and (vga processor) and (memory buffer)	USPAT; US-PGPUB; EPO; JPO	2004/07/2 1 17:39		
137	BRS 1	"6317124".PN.	USPAT	2004/07/2 1 16:48		
138	BRS 1	"5712664".PN.	USPAT	2004/07/2 1 16:48		
139	BRS 1	"5008838".PN.	USPAT	2004/07/2 1 16:50		
140	BRS 47	345/806.ccls.	USPAT; US-PGPUB; EPO; JPO	2004/07/2 1 18:30		

09/27/01 286  
28  
25-04

Type	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition
141	BRS 489	345/781.ccls.	USPAT; US-PGPUB; EPO; JPO	2004/07/21 18:30		
142	BRS 67	345/781.ccls. and (multiple plural) near (screen panel display monitor)	USPAT; US-PGPUB; EPO; JPO	2004/07/21 18:41		
143	BRS 61	345/781.ccls. and (multiple plural) near (panel display monitor)	USPAT; US-PGPUB; EPO; JPO	2004/07/21 18:41		
144	BRS 5	345/541.ccls. and 345/505.ccls.	USPAT	2004/07/21 19:23		
145	BRS 0	09/673612	USPAT; US-PGPUB; EPO; JPO	2004/07/21 19:23		